



Obsolete Chuck Crossover

AT+ Number		ATSC
A	B	C
3AT+4	A0100176977	B8043S
6AT+4	A0100211977	B8046S
3AT+5	A0100177977	B8053S
6AT+5	A0100212977	B8056S
3AT+6	A0100178977	B8063S
6AT+6	A0100213977	B8066S
3AT+6R	A0100178978	B8063
6AT+6R	A0100213978	B8066
3AT+8	A0100179977	B8083S
6AT+8	A0100214977	B8086S
3AT+8R	A010079978	B8083
6AT+8R	A0100214978	B8086
3AT+10	A0100180977	B8103S
6AT+10	A0100215977	B8106S
3AT+10R	A0100180978	B8103
6AT+10R	A0100215978	B8106
3AT+12	A0100181977	B8123S
6AT+12	A0100216977	B8126S
3AT+12R	A0100181978	B8123
6AT+12R	A0100216978	B8126
3AT+15R	A0100182978	B8153
6AT+15R	A0100217978	B8156

The chart to the left refers to the replacement options for the obsolete AT+ model of chucks. The ATSC was designed as a replacement for this chuck- the components are not interchangeable, but the ATSC can be mounted to the existing adapter plate from your AT+ chuck.

If you currently have an AT+ with any of the numbers in column A or B, it is replaced by a chuck in column C. Please contact us at 1-800-228-BUCK for more information.

AT Number		AT Number	BVC Number
A	B	C	D
3AT4	A1434	1434	**
6AT4	A1462	1462	**
3AT5	A2535	2535	**
6AT5	A2562	2562	**
3AT6	A0002063003	3634	**
6AT6	A0002066003	3662	**
3AT6R	A0002063002	2063R	B2063R
6AT6R	A0002066002	2066R	B2066R
3AT8	A0002083003	4831	**
6AT8	A0002086003	4862	**
3AT8R	A0002086002	2083R	B2083R
6AT8R	A0002086002	2086R	B2086R
3AT10	A0002103003	5103	**
6AT10	A0002106003	5106	**
3AT10R	A0002103002	2103R	B2103R
6AT10R	A0002106002	2106R	B2106R
3AT12	A0002124003	5124	**
6AT12	A0002127003	5127	**
3AT12R	A0002124002	2124R	B2124R
6AT12R	A0002127002	2127R	B2127R
3AT15R	A0002154002	2154R	B2154R
6AT15R	A0002157002	2157R	**

The chart to the left refers to the replacement options for the obsolete AT model of chucks. The BVC was designed as a replacement for this chuck- the components are not interchangeable, but the BVC can be mounted to the existing adapter plate from your AT chuck.

If you currently have an AT with any of the numbers in column A, B or C, it is replaced by a chuck in column D. The chucks that have ** in column D do not have a direct replacement, but there are alternate replacement options available that may not require you to purchase a new adapter plate. Please contact us at 1-800-228-BUCK for more information.